

WARRANTY REFERENCE NO.

0450089

OWNER'S NAME LAST MILLER FIRST MARK
ADDRESS 4500 SCARLET OAK DR AREA CODE 228 PHONE 497-6328
CITY GAUTIER STATE MS ZIP 39553
EMAIL ADDRESS

PLEASE PRINT - LEAVE SPACE BETWEEN WORDS

UNIT APPLICATION ☒ NON-COMMERCIAL ☐ COMMERCIAL ☐ RENTAL

DELIVERY DATE MO 06 DAY 28 YR 07

SALESPERSON'S S/S NUMBER & NAME
(AS APPLICABLE)



LAST FIRST

FRAME NO.

BACJ-1500210

HONDA CODE

646620

PURCHASING DLR. NO.

313048

MODEL

BF225AKX

ENGINE NO.

EEAGJ-1105462

PRE-DELIVERY CERTIFICATION

I hereby certify that prior to delivery to the first retail purchaser, set-up and pre-delivery servicing was performed on this unit in accordance with the instructions contained in the set-up and pre-delivery service check list.

SELLING DLR. NO. 3113048

SELLING DLR. ZIP 39564


DEALERSHIP OFFICER OR OWNER'S SIGNATURE

DATE SIGNED MO 06 DAY 28 YR 07

SHADED AREAS MUST BE FILLED OUT COMPLETELY
CUSTOMER COPY

OCEAN MARINE GROUP, INC.

5927 Washington Avenue
Ocean Springs, MS 39564
(228) 818-0200
FAX (228) 818-0202

CUSTOMER'S ORDER NO.		PHONE		DATE	
		228-497-6328		6-28-07	
NAME					
MARK P. MILLER					
ADDRESS					
4500 SCARLET OAK DR					
CITY					
Gautier, MS. 39553					
STATE					
ZIP					
PAID BY					
CASH					
C.O.D.					
CREDIT					
ON-ACC					
MIS. RET'D					
PAID OUT					
REPAIR					
QTY	PART NO.	DESCRIPTION		PRICE	AMOUNT
		Honda BF225AKX - new		\$ 14348.00	
		BAG-I-1500210			
		credit - Honda warranty			791.00
				\$ 13557.00	
		parts			49.90
				\$ 13606.90	
RECEIVED BY: 					7% TAX 952.48
					TOTAL \$ 14559.38

B. PRODUCT WARR

All claims and returned goods MUST be accompanied by this bill.

54934

 To Reorder
800-225-6380 or nabes.com

Thank You!



Ocean Marine Group, Inc.
 5927 Washington Avenue
 Ocean Springs, MS 39564
 (228) 818-0200

Invoice

2284976328

Mark P. Miller
 4500 Scarlet Oaks
 Gautier, MS 39553

Sales Code: PETE

Invoice No 10399
 Invoice Date 11/09/12
 Work Order No 1756
 Date In 10/29/12

Unit Information:

Reg No: MI-0244-BA
 Make: PROLINE Model: 240
 Motor1:
 Year: 2007 Make: HONDA Model: BF225AKX HP: 225 Serial No: BAGJ-1500210

Job No Job Description

1

s/b ecu and o2 sensor

Correction

we replaced o2 sensor and ecu, hours on motor 1160

Warranty Claim Claim No 1756 Honda Marine

Part No	Make	Dept	Description	Qty
06356-ZY3-325	HON	PARTS	KIT O2 SENSOR	1.00
Code	Tech	Description		
07	TM	HONDA WARRANTY		

Job No Job Description

2

install boot on motor were cables connect

Correction

we installed boot back on motor

*****Internal Work Order***** Stock No

Code	Tech	Description
LABOR	TM	SHOP LABOR

Job No Job Description

3

pee/tube stopped up

Correction

we removed dirt from hose

Payable By Customer

Code	Tech	Description	Hrs/Qty	Rate	Total
LABOR	TM	SHOP LABOR	0.10	90.00	9.00
Labor Sub Total					9.00

Job No Job Description

4

replace spark plugs, motor run's rough but last time out ok

Correction

we replaced spark plugs and had to replace a busted hose behind vst tank

Payable By Customer

<u>Part No</u>	<u>Make</u>	<u>Dept</u>	<u>Description</u>	<u>Qty</u>	<u>Price Each</u>	<u>Total</u>
IZFR6F11	MED	ACC	6	1.00	18.29	18.29
19258-ZY3-010	HON	PARTS	TUBE, WATER INLET	1.00	3.10	3.10
Parts Sub Total						21.39
<u>Code</u>	<u>Tech</u>	<u>Description</u>	<u>Hrs/Qty</u>	<u>Rate</u>	<u>Total</u>	
LABOR	TM	SHOP LABOR	2.50	90.00	225.00	
Labor Sub Total					225.00	

Job No
5

Job Description

Correction

replace timming belt and check bearings around belt

we replaced timming belt and checked bearings ok

Payable By Customer

<u>Part No</u>	<u>Make</u>	<u>Dept</u>	<u>Description</u>	<u>Qty</u>	<u>Price Each</u>	<u>Total</u>
14400-P8A-A02	HON	PARTS	BELT, TIMING	1.00	48.52	48.52
Parts Sub Total						48.52
<u>Code</u>	<u>Tech</u>	<u>Description</u>	<u>Hrs/Qty</u>	<u>Rate</u>	<u>Total</u>	
LABOR	TM	SHOP LABOR	2.00	90.00	180.00	
Labor Sub Total					180.00	

Job No
6

Job Description

Correction

change gear lube

we changed gear lube

Payable By Customer

<u>Part No</u>	<u>Make</u>	<u>Dept</u>	<u>Description</u>	<u>Qty</u>	<u>Price Each</u>	<u>Total</u>
ACC-GEARL-UB-0	YAM	PARTS	GEARLUBE 5 GALLON PA	30.00	0.66	19.80
Parts Sub Total						19.80
<u>Code</u>	<u>Tech</u>	<u>Description</u>	<u>Hrs/Qty</u>	<u>Rate</u>	<u>Total</u>	
LABOR	TM	SHOP LABOR	0.10	90.00	9.00	
Labor Sub Total					9.00	

Sales Tax 35.89

Amount Due By Customer 548.60

Paid VISA 548.60

Balance Due 0.00

HULL PLUG HAS BEEN REMOVED, CHECK HULL PLUG PRIOR TO LAUNCHING BOAT.



Ocean Marine Group, Inc.
5927 Washington Avenue
Ocean Springs, MS 39564
(228) 818-0200
(228) 822-2633

CASH
Cash Sale

Invoice

Invoice No 8523
Date 7/02/12
Sales Code PETE

#	Make	Dept	Part No	Description	Qty	Price	Extended
1	HON	PARTS	35655-ZY3-013	SENSOR, OXYGEN	1.00	197.21	197.21
2	MED	ACC	3207029	Element-S-Thr320R	1.00	29.99	29.99
Payment Method		VISA	\$243.10	Sub Total			227.20
				State/Fed Tax			15.90
				Invoice Total			243.10
		Change Due	0.00	Amt Paid/Deposits			243.10

Ocean Marine Group, Inc.
5927 Washington Avenue
Ocean Springs, MS 39564
(228) 818-0200

Invoice

2284976328
Mark P. Miller
4500 Scarlet Oaks
Gautier, MS 39553

Sales Code: MB

Invoice No 5647
Invoice Date 1/26/12
Work Order No 882
Date In 1/09/12

Unit Information:

Reg No: MI-0244-BA
Make: PROLINE Model: 240
Motor1:
Year: 2007 Make: HONDA Model: BF225AKX HP: 225 Serial No: BAGJ-1500210

Job No 1
Job Description

REPLACE COOLING SYSTEM has never had any cooling system work done, horn going off, look at customer notes

Correction

we replaced water pump broke off 4 bolts, thermostats, had to remove mid section, replaced with used section had to replace vertical bushing, we also replaced fuel filters. we found hose busted behind vst tank which was spliced by another dealer, replaced hose

Payable By Customer

<u>Part No</u>	<u>Make</u>	<u>Dept</u>	<u>Description</u>	<u>Qty</u>	<u>Price Each</u>	<u>Total</u>
06193-ZY3-000	HON	PARTS	PUMP KIT, IMPELLER	1.00	165.84	165.84
40210-ZY3-610	HON	PARTS	BUSH, VERTICAL SHAFT	1.00	28.98	28.98
3977026	MED	ACC	Brush-Tube	1.00	24.29	24.29
40210-ZY3-610	HON	PARTS	BUSH, VERTICAL SHAFT	1.00	28.98	28.98
16911-ZY3-010	HON	PARTS	SCREEN	2.00	33.11	66.22
16911-ZY3-010	HON	PARTS	SCREEN	-1.00	33.11	-33.11
19300-ZY3-023	HON	PARTS	THERMOSTAT ASSY.	2.00	33.88	67.76
91356-SD4-952	HON	PARTS	O-RING (31.5X2.4)	2.00	2.58	5.16
16078-ZY3-000	HON	PARTS	O-RING	1.00	10.56	10.56
XXX		ACC	SHOP SUPPLIES	1.00	10.00	10.00
Parts Sub Total						374.68
<u>Code</u>	<u>Tech</u>	<u>Description</u>	<u>Hrs/Qty</u>	<u>Rate</u>	<u>Total</u>	
LABOR	TM	SHOP LABOR	5.00	90.00	450.00	
Labor Sub Total					450.00	

Job No 2
Job Description

hull has a leak in it

Correction

took boat to water found transducer leaking at wire coming out of transome, resealed

Payable By Customer

Code	Tech	Description	Hrs/Qty	Rate	Total
RIGLBR	TM	Rigging Labor	1.00	65.00	65.00
Labor Sub Total					65.00

Job No 3
Job Description

engine knocks when first started

Correction

replaced exhaust pipes buste, MOTOR HAS 991 HOURS ON MOTOR

Payable By Customer

Part No	Make	Dept	Description	Qty	Price Each	Total
18333-ZY3-003	HON	PARTS	GASKET, EX. PIPE	2.00	6.80	13.60
18340-ZY3-020	HON	PARTS	PIPE, L. EX.	1.00	168.14	168.14
18330-ZY3-020	HON	PARTS	PIPE, R. EX.	1.00	163.22	163.22
90122-ZY3-000	HON	PARTS	BOLT, HEX. (12X50)	2.00	5.66	11.32
16081-ZW5-010	HON	PARTS	SCREW-WASHER	3.00	3.82	11.46
90124-ZY3-000	HON	PARTS	BOLT, STUD (12X40)	1.00	6.78	6.78
90126-ZY3-000	HON	PARTS	BOLT, HEX. (10X47)	3.00	6.90	20.70
XXX		ACC	exhaust housing used	1.00	355.00	355.00
Parts Sub Total						750.22
Code	Tech	Description	Hrs/Qty	Rate	Total	
LABOR	TM	SHOP LABOR	8.00	90.00	720.00	
Labor Sub Total					720.00	

Job No
4

Job Description

replace control cables, and short steering hoses

Correction

we replaced control box and cables, cables busted, and control box full of corrosion, HELM IS BAD CUSTOMER SAID HE WOULD REPAIR HELM

Payable By Customer


<u>Part No</u>	<u>Make</u>	<u>Dept</u>	<u>Description</u>	<u>Qty</u>	<u>Price Each</u>	<u>Total</u>
4061692	MED	ACC	4 Ft Hose	1.00	111.99	111.99
06240-ZW5-U40	HON	PARTS	BOX KIT	1.00	257.49	257.49
4062101	MED	ACC	CABLE-CNTRL 22' 3300 XTRE	2.00	55.99	111.98
Parts Sub Total						481.46
<u>Code</u>	<u>Tech</u>	<u>Description</u>	<u>Hrs/Qty</u>	<u>Rate</u>	<u>Total</u>	
RIGLBR	TM	Rigging Labor	2.00	65.00	130.00	
Labor Sub Total					130.00	

Invoice Summary

Parts Total	1,606.36
Labor Total	1,365.00
Sales Tax	208.00
Grand Total	3,179.36
Amount Due By Customer	3,179.36
Paid VISA	3,179.36
Balance Due	0.00

HULL PLUG HAS BEEN REMOVED, CHECK HULL PLUG PRIOR TO LAUNCHING BOAT.

OCEAN MARINE GROUP, INC.
 5927 Washington Avenue
 Ocean Springs, MS 39564
 (228) 818-0200
 FAX (228) 818-0202

QTY.	PART NO. and DESCRIPTION	AMOUNT
①	724162 Jack	87.95
①	Fuel Filter	13.00
①	Oil Filter	9.99
①	24002 Kit	84.95
⑧	9460W30	335.2680
①	Gear Lub	15.00
①	STD Supplies	500
<hr/>		
1st Service Charge 100.00		
Greased Charge Lub		
Casey to STD to 2000		
There is still water in tank		
Drained water from 1st		
Replace Filter Assy. 1st		
Replace 1st Stand		
1st ACAM Goes off DRAIN 1st		
Tank and Race Filter.		
Change manually		
Replace 2nd Filter		
and 2nd		
Re attached fuel filter		
at level 400 #43		
		
TOTAL PAGES 07		

INWAY BE CONTINUED ON OTHER SIDE

Mark

From: Ocean Marine Group [omgroup@bellsouth.net]
Sent: Tuesday, January 10, 2012 8:02 AM
To: bb@primo.ws
Subject: RE: Attn: Service Department - Repair List for PRIMOFISH

Am bringing to him now.
Thanks

From: Mark [mailto:MarkPrimo@primo.ws]
Sent: Tuesday, January 10, 2012 7:37 AM
To: omgroupp@bellsouth.net
Subject: FW: Attn: Service Department - Repair List for PRIMOFISH

Stacy has not returned my call. Could you please acknowledge receipt of this Repair List and delivery to Stacy? Thanks!

Mark P Miller, P.E.
228-218-9523

<http://www.primoengineering.com>

<http://www.primofish.com/fishing.htm>

<http://www.youtube.com/MarkPrimo>

<http://www.facebook.com/MarkPrimo>

From: Mark [mailto:MarkPrimo@primo.ws]
Sent: Monday, January 09, 2012 7:25 AM
To: 'omgroup@bellsouth.net'
Subject: Attn: Service Department - Repair List for PRIMOFISH

Repair List for PRIMOFISH.COM - 24' Proline, Red & White

1. Overhaul Cooling System.

- a) **Replace Impeller and Housing and clear all passages.** Engine does not pee and I am getting intermittent overheating alarm. Red Light comes on, buzzer sounds continuously, and Engine RPMs drop. I believe the alarm may be in error because I can turn the key off, immediately restart, and resume normal operations for 30 minutes to an hour before alarm comes on again. However, it is time to replace moving parts in the cooling system, so please do so.
- b) I have always had a problem with this **Engine not peeing since it was new**. After every Service, it would work for a half dozen trips and then stop. However I always had good water pressure and tended to ignore the problem. My previous Honda never had this problem.
- c) Also the **water pressure gauge is not zeroed** out anymore. If this is an easy fix, please do so. If it requires gauge replacement, only do so if covered under warranty. It does not bother me that much.
- d) During the last Service at Empress Marine, it was reported that a **hose had gotten a hole rubbed into it** causing it to not pee. However, instead of replacing the hose, they put a coupler in it. Please replace the entire hose if practical. If not practical, please call me to explain the situation.
- e) Also, Since the Engine was new, I have had an alarm issue where the boat would go over a wave and jar the Engine and an alarm would come on, the Engine would run extremely rough, and RPMs would drop (**Torque Alarm?**). I could turn the key off, immediately restart, and resume normal operations. This was

reported during all previous Service routines, but no problems could ever be found. Just FYI in case current Diagnostic Computer Software can help resolve this issue.

2. **Hull Leak Diagnostics.** I have a **leak in the hull** that I cannot seem to track down. I suspect either it is coming from inside the Engine Mounting Bracket or coming through where the Gel Coat has rubbed off the bottom of the Hull or thru some screw holes. You can put water in the hull and see it leaking out, but it is difficult to determine the source. I would like your opinion on the source and remedy.
3. **Repair Cabin Door Latch.** It does not need to be the same latch, just something functional.
4. **Shift and Throttle Cables.** I have had problems with **stiff cables again**, mostly shifting. It seems better lately, but due to the difficulty of getting the boat into the shop, I am inclined to replace them. Please call me to discuss pricing and options such as control upgrades.
5. **Engine Knocks when first Started.** An Engine Knock has developed that is noticeable when the Engine is first cranked cold. It will knock for about 2-3 minutes or so and then quiet down. It started this about 6 months ago and does not seem to cause any problems, but I would like your opinion if something needs to be done (Oil Pump? Higher Octane Fuel?). I have always used high quality synthetic oil, currently Mobile One.

Please feel free to call me on my cell phone at anytime (218-9523).

Mark P Miller, P.E.

4500 Scarlet Oak Dr

Gautier, MS 39553

228-218-9523


<http://www.primoengineering.com>


<http://www.primofish.com/fishing.htm>

<http://www.youtube.com/MarkPrimo>

<http://www.facebook.com/MarkPrimo>

OCEAN MARINE GROUP, INC.
 5927 Washington Avenue
 Ocean Springs, MS 39564
 (228) 818-0200
 FAX (228) 818-0202


QTY.	PART NO. and DESCRIPTION	AMOUNT
1	41100-Z143-A142A	3109.80
1	02 sensor 36655-24203	192.21 (2)
(1) Replaced sensor case looked up no use fish line around prop shaft R/R		
(2) 02 sensor - showed R/R (2)		
		
(MAY BE CONTINUED ON OTHER SIDE)		
TOTAL PARTS		

9313		<input type="checkbox"/> RETAIL <input type="checkbox"/> WARRANTY <input type="checkbox"/> ESTIMATE		ORDER WRITTEN BY
NAME Mark Miller		DATE RECEIVED 8-28-09		DATE PROMISED 9-4-09
ADDRESS		PHONE		DATE COMPLETED
CITY		STATE		ZIP
PRODUCT MAKE MODEL Honda 225	ENGINE MAKE/MODEL Honda 225	SERIAL NO. ENGINE #1 B465-1500810	SERIAL NO. DRIVE #1	
TANKS	BATTERY	KEY NO.	REGISTRATION NO. MI-08461-B4	SERIAL NO. ENGINE #2
NATURE OF SERVICE REQUEST		STORAGE FROM TO		
DESCRIPTION OF WORK				
Hour going off motor lost power did then recheck and found good check out				
				
AMOUNT				
TOTAL LABOR		135.00		
TOTAL PARTS		3109.80		
OUTSIDE REPAIRS		<input type="checkbox"/> LAUNCH <input type="checkbox"/> DELIVER <input type="checkbox"/> CHAD-OUT <input type="checkbox"/> PICK-UP		
SUB-TOTAL		3244.80		
TAX		227.13		
GAS				
TOTAL		3471.92		

CHECK DRAIN PLUG

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate the unit herein described on any waterways or elsewhere for purposes of testing, inspection, or delivery at my risk. An express mechanic's lien is acknowledged on above unit to secure the amount of repairs thereon. It is also understood that you will not be held responsible for loss or damage to the unit (or articles left in or with the unit) in case of fire, theft, accident, inclement weather conditions or any other cause beyond your control.

AUTHORIZED BY





Ocean Marine Group, Inc.
 5927 Washington Avenue
 Ocean Springs, MS 39564
 (228) 818-0200

Invoice

2284976328
 Mark P. Miller
 4500 Scarlet Oaks
 Gautier, MS 39553

Sales Code: JA

Invoice No 5846
 Invoice Date 2/17/12
 Work Order No 952
 Date In 2/09/12

Unit Information:

Reg No: MI-0244-BA
 Make: PROLINE Model: 240
 Motor1:
 Year: 2007 Make: HONDA Model: BF225AKX HP: 225 Serial No: BAGJ-1500210

Job No 1
 Job Description
 need estimate on replacing steering head
 Correction
 we replaced steering head and mount kit

Payable By Customer

<u>Part No</u>	<u>Make</u>	<u>Dept</u>	<u>Description</u>	<u>Qty</u>	<u>Price Each</u>	<u>Total</u>
4069294	MED	ACC	Front Mount Helm	1.00	586.99	586.99
4061468	MED	ACC	A Back Mount Kit	1.00	35.99	35.99
XXX		ACC	steering fluid	1.00	20.00	20.00
Parts Sub Total						642.98
<u>Code</u>	<u>Tech</u>	<u>Description</u>	<u>Hrs/Qty</u>	<u>Rate</u>	<u>Total</u>	
RIGLBR	TM	Rigging Labor	2.00	65.00	130.00	
Labor Sub Total					130.00	

Job No 2
 Job Description
 water leak under hood
 Correction
 pea hose busted from sand packed in hose, we removed stbd cowling to replace hub

Payable By Customer

<u>Part No</u>	<u>Make</u>	<u>Dept</u>	<u>Description</u>	<u>Qty</u>	<u>Price Each</u>	<u>Total</u>
91404-ZY3-000	HON	PARTS	TUBE, WATER CHECK	1.00	1.50	1.50
Parts Sub Total						1.50
<u>Code</u>	<u>Tech</u>	<u>Description</u>	<u>Hrs/Qty</u>	<u>Rate</u>	<u>Total</u>	
LABOR	TM	SHOP LABOR	0.50	90.00	45.00	
Labor Sub Total					45.00	

Job No 3
 Job Description
 need a latch for console door
 Correction
 did not repair

Payable By Customer

Job No 4
 Job Description
 boat still has a leak check at livewell pump
 Correction
 we resealed a hole in transome, we sealed same hole inside, it looks like the gil-bracket needs to come off and reseat or transome is weak and needs replacing, all of the deck fittings are leaking and covers need replacing, if boat is caught in the rain it will drain into bilge

*****Internal Work Order***** Stock No

<u>Code</u>	<u>Tech</u>	<u>Description</u>
RIGLBR	TM	Rigging Labor

Job No
5

Job Description

Correction
check water psi gauge sticking
bad gauge, full of corrosion

Payable By Customer

<u>Code</u>	<u>Tech</u>	<u>Description</u>	<u>Hrs/Qty</u>	<u>Rate</u>	<u>Total</u>
RIGLBR	TM	Rigging Labor	0.20	65.00	13.00
Labor Sub Total					13.00

Invoice Summary

Parts Total	644.48
Labor Total	228.00
Sales Tax	58.27
Grand Total	930.75
Internal Paid By Dealer	40.00
Amount Due By Customer	890.75
Paid VISA	890.75
Balance Due	0.00

HULL PLUG HAS BEEN REMOVED, CHECK HULL PLUG PRIOR TO LAUNCHING BOAT.