



DEALER COPY
KOBY
IMPORT AUTO

1431 E I65 Service Road S
Mobile AL 36606
Phone: 251-473-3203

12/28/2020 12:08:41

Customer No. Primary Driver DEALER KOBY IMPORT AUTO	License #	Stock # 31125S	Dealer # 040647	Invoice Date 12/28/2020	Invoice # 111345
Customer Name & Address KOBY IMPORT AUTO 1431 SOUTH I-65 SERVICE ROAD SOUTH MOBILE, AL 36606 2512135876	Mileage In 4852	Mileage Out 4852	Lot #/Hat #	Color RED	Delivery Date 06/13/2018
	Year/Make/Model 2018 SUBARU CROSSTREK			Prod Date / /	R.O. Date 12/26/2020
	Vehicle ID # JF2GTAMCXJH266971			Tech & #	P.O. #
	Override	Service Write Up MYLA BLACKWELL		S.W. INT. EST.	Engine Hours
Extended Warranty Co. SUBARU ADDED SECURIT	Policy #	Deductible		Auth. #	Adjustor
Residence Phone 2514785000	Business Phone 2514785000	Cellphone 2512135876	Service Writer Delivery Signature		

Type: I JOB # 1 Tech: BRANDON WRIGHT

OP Code:

Complaint: Perform Subaru Certified Vehicle Inspection

Correction: Perform Subaru Certified Vehicle Inspection

Tech	Flag	Clock	Warr	Fail	QC
1: 426	1.20	1.66			

Punch In	Punch Out	Hours
12/28/2020 09:48:19 AM	12/28/2020 11:27:52 AM	1.66

JOB TOTALS Labor: \$115.00 Parts: \$0.00

TOTAL: \$115.00

Type: I JOB # 2 * Tech: BRANDON WRIGHT

OP Code:

Complaint: Perform 30,000 mile factory service. Replace engine oil, engine oil filter, brake fluid, and engine air filter, also rotate tires.

Cause: Inspect drive belts, fuel lines, cooling system, engine air filter, transmission gear oil, front and rear differential gear oil, disc brake pads, brake linings, suspension, axle boots, and steering system.

Correction: Perform factory 30,000 mile service

Part:	15208AA15A	OIL FILTER COMPLETE	Qty:	1	\$7.25
Part:	803916010	GASKET	Qty:	1	\$1.99
Part:	SOA635045	SYNTHETIC 0W-20 OIL QT	Qty:	6	\$45.00
Part:	16546AA16A	ELEMENT AIR CLEANER	Qty:	1	\$21.26
Part:	SOA868V9110	N/C BRAKE CLEANER	Qty:	1	\$5.46
Part:	SOA868V9221	BRAKE FLUID	Qty:	1	\$7.04
Tech	Flag	Clock	Warr	Fail	QC
1: 426	1.80	0.00			

JOB TOTALS Labor: \$225.69 Parts: \$88.00

TOTAL: \$313.69

Type: I JOB # 3 * Tech: BRANDON WRIGHT

OP Code:

Complaint: Perform Drivetrain service. Includes replacing front differential fluid and drain gasket, replacing rear differential fluid and drain gasket.

Correction: Perform Drivetrain service. Includes replacing front differential fluid and drain gasket, replacing rear differential fluid and drain gasket.

Part:	SOA427V1700	HIGH PERF GEAR OIL 75W-90	Qty:	3	\$37.26
Part:	803926090	GASKET 26.3X32.3X1	Qty:	1	\$2.40
Tech	Flag	Clock	Warr	Fail	QC
1: 426	1.20	0.48			

Punch In	Punch Out	Hours
----------	-----------	-------

Extended Warranty Pay	Factory Warranty Pay	Internal Pay 961.17	All labor charges are billed on flat rate hours unless otherwise noted.	Total Customer Pay
-----------------------	----------------------	------------------------	---	--------------------



DEALER COPY

KOBY

IMPORT AUTO



1431 E I65 Service Road S

Mobile AL 36606

Phone: 251-473-3203

12/28/2020 12:08:41

Customer No.	Primary Driver	License #	Stock #	Dealer #	Invoice Date	Invoice #
DEALER	KOBY IMPORT AUTO		31125S	040647	12/28/2020	111345

JOB TOTALS	Labor:\$139.95	Parts: \$39.66	TOTAL:\$179.61
-------------------	-----------------------	-----------------------	-----------------------

Type: I JOB # 4 * Tech:BRANDON WRIGHT

OP Code:

Complaint: Replace battery clean terminal ends, verify proper operation

Correction: Perform battery replacement

Part:	SOA591B726	PB001826 26" BEAM WIPER B	Qty:	1	\$28.09
Part:	SOA591B716	16" BEAM WIPER BLADE (PAS	Qty:	1	\$28.09
Part:	SOA591R612	12" REAR WIPER BLADE	Qty:	1	\$12.80
Tech	Flag	Clock	Warr	Fail	QC
1: 426	0.50	0.00			

JOB TOTALS	Labor:\$39.95	Parts: \$68.98	TOTAL:\$108.93
-------------------	----------------------	-----------------------	-----------------------

Type: I JOB # 5 * Tech:BRANDON WRIGHT

OP Code:

Complaint: Customer requests wiper blade replacement

Correction: Replace wiper blades

Part:	SOA821B200	PB001721 BATTERY	Qty:	1	\$154.88
Tech	Flag	Clock	Warr	Fail	QC
1: 426	0.20	0.00			

JOB TOTALS	Labor:\$10.00	Parts: \$154.88	TOTAL:\$164.88
-------------------	----------------------	------------------------	-----------------------

Type: I JOB # 6 * Tech:BRANDON WRIGHT

OP Code:

Complaint: Replace Cabin Air Filter

Correction: Replace Cabin Air Filter

Part:	72880FL00A	FILTER	Qty:	1	\$22.06
Tech	Flag	Clock	Warr	Fail	QC
1: 426	0.20	0.00			

JOB TOTALS	Labor:\$22.05	Parts: \$22.06	TOTAL:\$44.11
-------------------	----------------------	-----------------------	----------------------

Type: I JOB # 7 * Tech:BRANDON WRIGHT

OP Code:

Complaint: Customer states tire is not retaining correct pressure

Cause: nail in tread of right front tire

Correction: Repair tire with patch plug system

Tech	Flag	Clock	Warr	Fail	QC
1: 426	0.50	0.00			

JOB TOTALS	Labor:\$34.95	Parts: \$0.00	TOTAL:\$34.95
-------------------	----------------------	----------------------	----------------------

CUSTOMER TOTALS: \$0.00

WE STRIVE FOR THE BEST CUSTOMER EXPERIENCE POSSIBLE. IF FOR
ANY REASON YOU DIDN'T HAVE AN "EXCEPTIONAL" EXPERIENCE
PLEASE CONTACT HAYLEY COLLIER AT 251-517-1643

Extended Warranty Pay	Factory Warranty Pay	Internal Pay 961.17	All labor charges are billed on flat rate hours unless otherwise noted.	Total Customer Pay
-----------------------	----------------------	------------------------	--	--------------------



DEALER COPY

KOBY

IMPORT AUTO



1431 E I65 Service Road S

Mobile AL 36606

Phone: 251-473-3203

12/28/2020 12:08:41

Customer No.	Primary Driver	License #	Stock #	Dealer #	Invoice Date	Invoice #
DEALER	KOBY IMPORT AUTO		31125S	040647	12/28/2020	111345

THANK YOU FOR YOUR BUSINESS

Cash ☐ _____ Check ☐ _____ Credit Card ☐ _____

Customer Signature X _____

Extended Warranty Pay	Factory Warranty Pay	Internal Pay 961.17	All labor charges are billed on flat rate hours unless otherwise noted.	Total Customer Pay
-----------------------	----------------------	------------------------	--	--------------------

