



**Ocean Marine Group, Inc.**  
 5927 Washington Avenue  
 Ocean Springs, MS 39564  
 (228) 818-0200

Customer No 2284976328  
 Mark P. Miller  
 4500 Scarlet Oaks  
 Gautier, MS 39553

Date In 3/03/14 Work Order No 2975  
 Service Writer: mh Miles/Hrs  
 Estimated Completion Date In Service Date 6/07/07  
 Service Contract

HOME (228) 497-6328 CELL (228) 218-9523

Assigned Tech: TM

Unit Information

Reg No: MI-0244-BA  
 Make: PROLINE Model: 240  
 Motor1:  
 Year: 2007 Make: HONDA Model: BF225AKX HP: 225 Serial No: BAGJ-1500210

Job No Job Description

1



Customer says motor is not running good at all towards WOT, very rough  
 Diagnos and call

Correction

Motor has corrosion and rust throughout. Water in cylinders, causing motor to miss and run rough. Oil is full of water.  
 New starter, coils, plugs, plug wires, heads, etc. Hull is damaged, water entering @ bilge plug.

**Payable By Customer**

<u>Code</u>	<u>Tech</u>	<u>Description</u>	<u>Hrs/Qty</u>	<u>Rate</u>	<u>Total</u>
LABOR	TM	SHOP LABOR	1.00	90.00	90.00
Labor Sub Total					90.00

Tech Notes:

Date: \_\_\_\_\_ Technician: \_\_\_\_\_ Hours: \_\_\_\_\_

Order Summary

Labor Total	90.00
Sales Tax	6.30
Grand Total	96.30
Amount Due By Customer	96.30

HULL PLUG HAS BEEN REMOVED, CHECK HULL PLUG PRIOR TO LAUNCHING BOAT.